

Main Office
415 Route 10 East
Randolph, NJ 07869
Phone: (800) 831-5771
Fax: (973) 537-1420

Engineering Group
101 N. Plains Industrial Rd
Wallingford, CT 06492
Phone: (203) 265 - 7022
Fax: (203) 265 - 3588

www.visitorwatch.com
info@visitorwatch.com




How To Disable The Corex Business Card Scanner

If you are receiving the 'File not found: cssdk32.dll - No.: 53' error message you probably have the Business Card scanner enabled w/ no Business Card scanner connected.

If you have a ScanShell 800 Driver's License scanner you can disable the Business Card scanner. You will still be able to scan business cards using the driver's license scanner as long as you have v6.02 or higher of Visitor Watch.

Follow these steps:

1. Go Utility → Peripheral Setup



2. Click on the Configuration tab, clear the Business Card Scanning check box, then click on close and exit out of Visitor Watch completely. When you log back into Visitor Watch you shouldn't see the 'File not found: cssdk32.dll - No.: 53' error message anymore.

